



EDMUND G. BROWN JR.
GOVERNOR



MATTHEW RODRIGUEZ
SECRETARY FOR
ENVIRONMENTAL PROTECTION

State Water Resources Control Board

December 22, 2017

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7016 3010 0000 5907 1745

Mr. Dennis Easto
Airport Manager
Oceanside Municipal Airport
480 Airport Road
Oceanside, California 92058
dennis.easto@oceansidemunicipalairport.com

**SUBJECT: NOTICE OF VIOLATION - NO FURTHER ACTION REQUIRED;
UNDERGROUND STORAGE TANK SYSTEMS LOCATED AT OCEANSIDE
MUNICIPAL AIRPORT, 480 AIRPORT ROAD, OCEANSIDE**

Dear Mr. Easto:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on November 29, 2017, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and California Code of Regulations (CCR), title 23, chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Monitor Tank – The site uses an automatic tank gauge to perform a monthly 0.2gph leak rate test on the single-walled tanks. The Veeder Root (VR) monitoring panel was not programmed to the correct continuous in-tank leak detection specifications of 99% probability of detection and in “enhanced mode.” The VR monitoring panel was reprogrammed at the time of inspections.	All	November 29, 2017	November 29, 2017	H&SC 25292(a); 23 CCR 2643(b)(1)

Office of Enforcement | 801 K Street, Suite 2300 | Sacramento, CA 95814 | 916.341.5272

FELICIA MARCUS, CHAIR | EILEEN SOBECK, EXECUTIVE DIRECTOR

1001 I Street, Sacramento, CA 95814 | Mailing Address: P.O. Box 100, Sacramento, CA 95812-0100 | www.waterboards.ca.gov

No.	Violation	Tank	Start Date	Stop Date	Regulation
2	Failure to Monitor Product Piping – The monitoring sensor in the piping sump was not able to detect a leak at the earliest opportunity because it was not in a vertical position or at the lowest point in the sump. The sensor was repositioned at the time of the inspection.	All	November 29, 2017	November 29, 2017	23 CCR 2641(a) & (j)
3	Failure to Maintain Plot Plan/Site Map – An approved plot plan/site map indicating the location of the product piping and auxiliary equipment with respect to buildings or other landmarks, such as the street, was not available in CERS or onsite at the time of the inspection.	All	November 16, 2017	December 7, 2017	23 CCR 2711(a)(8)

To our knowledge, the violations above have been corrected. Therefore no further action is required at this time. The State Water Board reserves the right to bring an action against the owner and/or operator of the tanks in violation, or it may recommend that San Diego County Environmental Health Department pursue enforcement, or San Diego County Environmental Health Department may elect to pursue enforcement independently

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,



Amantha Henkel
Senior Environmental Scientist
UST Enforcement Unit
Office of Enforcement

cc: See next page.

cc: *(via email only)*

Ms. Maryam Dorsey, Chief
Hazardous Material Division
Department of Environmental Health
County of San Diego
maryam.dorsey@sdcounty.ca.gov

Mr. Robert Rapista
Supervising Environmental Health Specialist
Underground Storage Tank Program
Department of Environmental Health
County of San Diego
robert.rapista@sdcounty.ca.gov

Mr. Josh Jones
Compliance Consultant
Rely Environmental
jjones@relyenvironmental.com